

TEST REPORT

Page 1 of 3

REPORT NUMBER: TURT140033823

APPLICANT NAME Gökhan Boya San. ve Tic. Ltd. Şti.

ADDRESS Kazımpaşa Mah. Çanakkale Asfaltı No:20 Menemen İzmir TÜRKİYE

FAX NO:0232 832 73 97

Attention : Ünal Şengün (unal@gokhanboya.com)

BUYER NOT GIVEN

SAMPLE DESCRIPTION: One sample of sharky polyurethane 2/1 pigmented glossy topcoat; white

DATE IN: 10 March, 2014 (09:45)

DATE OUT: 12 March, 2014 **YOUR REFERENCE:** 261-1001/279-0034

TEST	Sample
Safety of toys. Specification for Migration of Certain Elements	Р

P = MEETS BUYER' S REQUIREMENT / F = DOES NOT MEET BUYER' S REQUIREMENT / NR = NO REQUIREMENT / SC=STILL CONTINUES / X=NOT PERFORMED / NA = NOT APPLICABLE / LS : LACK OF SAMPLE

The test results relate only to the items tested. The whole and/or the part of this test report shall not be reproduced and shall not be shared with third parties, nor to be used for PR activities without the written permission of INTERTEK Test Hizmetleri A.S.

The reported uncertainity is based on a standard uncertainity multiplied by a coverage factor k=2, providing a level of confidence of approximately 95%. The uncertainity evaluation has been

The reported uncertainity is based on a standard uncertainity multiplied by a coverage factor k=2, providing a level of confidence of approximately 95%. The uncertainity evaluation has been carried out in accordance with ISO/IEC 17025 and TÜRKAK accreditation requirements. Unless otherwise is specified, all Pass or Fail results are given without uncertainity considered. When uncertainity is taken into account, the result may be borderline. Borderline results need to be re-tested to determine their disposition up to customer's decision. Opinions and interpretations expressed herein are outside the scope of TÜRKAK accreditation. Tests marked (*) in this test report are not included in the TÜRKAK accreditation schedule for this laboratory.

PP

Melek UNAL

Melahat YILDIRIM COORDINATOR

Simon of

Sinan ÖNCEL/ Customer Care Manager Özlem ÇAVUMİRZA/Textile Laboratory Manager



Intertek Test Hizmetleri A.S.

Merkez Mahallesi Sanayi Cad. No.23 Altindag Plaza Yenibosna 34197 - ISTANBUL / TURKEY Phone : +90.212. 496 46 46 Fax: +90.212. 452 80 55 e-mail : labtest.turkey@intertek.com

nail: labtest.turkey@intertek www.intertek-turkey.com





RESULTS Page 2 of 3

REPORT :TURT140033823 12 March, 2014

Test Method Result Requirements

Safety of toys. Specification for Migration of Certain Elements

BS EN 71-3: 1995

Acid extraction method was used and toxic elements content were determined by Inductively Coupled Plasma-ICP_OES.

		RESULT IN ppm	PASS/FAIL	Requirement (ppm)
Antimony	(Sb)	<2 ppm	PASS	60
Arsenic	(As)	<2 ppm	PASS	25
Barium	(Ba)	<2 ppm	PASS	1000
Cadmium	(Cd)	<2 ppm	PASS	75
Chromium	(Cr)	<5 ppm	PASS	60
Lead	(Pb)	<5 ppm	PASS	90
Mercury	(Hg)	<2 ppm	PASS	60
Selenium	(Se)	<2 ppm	PASS	500

ppm (Part per million) =mg / kg =Less Than ND =Not Detected





RESULTS Page 3 of 3

REPORT: TURT140033823 12 March, 2014

> **Test Method** Result Requirements



END OF TEST REPORT

